

DIRECTIONS:

INITIAL APPLICATION ON BARE WOOD FLOOR

1. Dust mop the floor using an untreated dust mop and vacuum.
2. Tack the floor with water or odorless mineral spirits using dust mop frame and lint-free towels. When tacking, overlap each lane.
3. Apply one coat of sanding sealer with a t-bar applicator, roller, lambs wool applicator, or brush. Allow to dry for 1-2 hours.
4. After the sealer has dried, lightly sand with a 175 rpm floor machine or 12"x18" orbital sander with a 180 grit sanding screen or maroon pad.
5. Dust mop floor with untreated mop and vacuum.
6. Tack the floor as outlined in step 2.
7. Shake or stir well for 30-45 seconds. Let product rest 15-20 minutes for best results.
8. Apply 2 coats of wood floor coating with a t-bar applicator, roller, lambs wool applicator, or brush. Allow the first coat to dry for 1-2 hours before applying the second coat. The floor will be fully cured in three days at normal temperature and humidity.

RECOAT

1. Dust mop floor using untreated mop.
2. Screen the floor using a 175 rpm floor machine and wood floor screens. The grit of the screens depends on the condition of the floor.
3. Follow steps 5 through 8 above.

KEEP OUT OF REACH OF CHILDREN. Keep container sealed when not in use. Keep from freezing. To avoid possible contamination, do not pour unused product from bucket back into original container.

FIRST AID:

EYE: Rinse with plenty of water. If irritation develops, seek medical attention. SKIN: Wash off with plenty of water. If irritation develops, seek medical attention. INHALATION: If breathing is difficult, remove to fresh air. If symptoms persist, seek medical attention. INGESTION: Do not induce vomiting. Seek medical attention.

CONTAINS:

diethylene glycol monoethyl ether (CAS# 111-90-0).

Safety Data Sheet available for download at pioneereclipse.com. FOR COMMERCIAL AND INDUSTRIAL USE ONLY.

Product Code	702FS	702MPE
Volume	2.50 US gallons	4 liters
Shipping Package	2 x 2.5 gallons	4 x 4 liters
Pallet Quantity	48	48